



State of Utah

Department of  
Natural Resources

ROBERT L. MORGAN  
*Executive Director*

Division of  
Oil, Gas & Mining

LOWELL P. BRAXTON  
*Division Director*

OLENE S. WALKER  
*Governor*

GAYLE F. McKEACHNIE  
*Lieutenant Governor*

November 19, 2004

CERTIFIED RETURN RECEIPT  
7099 3400 0016 8896 0402

Mr. Robert Clark  
1758 South 900 East  
Salt Lake City, Utah 84105

Subject: Division Directive, Robert Clark, Clark #1/Emeryside Mine, S/015/053,  
Emery County, Utah

Dear Mr. Clark:

On November 5, 2004, Division inspector Paul Baker met George Tetrault and Angela Wadman of the Price Office of the Bureau of Land Management at your mine site in Emery county. The purpose of this meeting was to talk about the potential for pieces of sandstone falling to the Miller Canyon Road as you and Mr. Baker have discussed previously.

The enclosed inspection report discusses the results of this meeting. There are several rocks that have been undermined or otherwise destabilized by mining, and while there is some potential for them to rotate away from the face and fall toward the road, it is unlikely they would make it to the road. ***However, it is important that you continue to monitor this situation and take what steps are necessary to prevent danger to the public.***

Since it appears mining has destabilized several areas of the face above the mine pad, and since further mining would likely make this situation worse, we have decided to issue the following Division Directive:

No mineral extraction, either underground or surface, is allowed in any area above the Miller Canyon Road until the face of the cliffs above the mine pad have been stabilized.


If you wish to appeal this directive, please contact Vicki Southwick at

Mr. Robert Clark  
Page 2 of 2  
S/015/053  
November 19, 2004

(801) 538-5304 with 10 days of your receipt of this letter to schedule an informal conference with the Associate Director of Mining to discuss this matter further.

If you have any questions regarding the requirements of this notice, please contact me at (801) 538-5325, or Paul Baker at 538-5261. Thank you for your cooperation in helping us resolve this public safety concern.

Sincerely,

A handwritten signature in black ink that reads "Daron R. Haddock". The signature is fluid and cursive, with the first name "Daron" being more prominent than the last name "Haddock".

Daron R. Haddock  
Permit Supervisor  
Minerals Regulatory Program

DRH:PBB:jb  
cc: Mark Mesch, OGM  
Paul Baker, OGM  
O:\M015-Emery\S0150053-RobertClark\final\dd-11192004.doc